## Approved For Release 2001/07/17: CIA-RDP74-00005R000100080043-9

## CHANGES & CORRECTIONS TO SECTION #3

- Direct connection of secondary safety circuit to hinge rather than behind magnet.
- 2. Re-tighten magnets to ensure good contact with safety circuit.
- 3. Bolts at every shelf--w/lock washer.
- 4. Repaired cold solder joints in power source cable.
- 5. Replaced control wiring from top of shelf to lower carriage.
- 6. Changed overhead arm extender supports.
- 7. Moved anti-tilt to edge of shelving.
- Relocated one chain return.
- Washers placed under control box to raise arm extender to acceptable height above boxes.
- 10. Eyebolts were installed at midpoints of shelves to support 'hip-level' secondary safety.
- 11. Adjusted rail stops to square up carriage.
- 12. Increased length of anchor bolts for rail installation where required.
- 13. Put a 2x4 under the shelf that is under the chain pick-up.
- 14. Secured plugs into overhead arm control box.